

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

MICHAEL O. LEAVITT Governor

OLENE S. WALKER Lieutenant Governor

Representatives Present During the Inspection			
Company	Vicky S. Miller Environmental Specialist		
OGM	Dana Dean Reclamation Specialist III		
	· · · · · · · · · · · · · · · · · · ·		

Inspection Report

Permit Number:	C0070018
Inspection Type:	COMPLETE
Inspection Date:	Thursday, September 18, 2003
Start Date/Time:	9/18/2003 8:30:00 AM
End Date/Time:	9/18/2003 10:10:00 AM
Last Inspection:	Tuesday, May 13, 2003

Inspector: Dana Dean, Reclamation Specialist III

Weather: Cool ~60 deg. F., Clear, Breezy

Accepted by: dhaddock 10/7/2003

Permitee:	CANYON	FUEL	COMPANY	LLC
Operator:	CANYON	FUEL	COMPANY	LLC

Site: SOLDIER CANYON MINE

Address: PO BOX 1029, WELLINGTON UT 84542

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current A	creages	Mineral Ownership	Types of Operations
6,624.64	Total Permitted	☐ Federal	Underground
24.32	Total Disturbed	☐ State	Surface
	Phase I	☐ County	Loadout
	Phase II	☐ Fee	Processing
	Phase III	Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Inspector's Signature:	Date	Monday, September 22, 2003
	2 4.19	

Dana Dean, Reclamation Specialist III

Inspector ID Number: 50

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070018
Inspection Type: COMPLETE

Inspection Date: Thursday, September 18, 2003

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		\checkmark	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures		~		
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation	✓		✓	
14.	Subsidence Control		✓		
15.	Cessation of Operations	✓		✓	
16.	a Roads: Construction, Maintenance, Surfacing	✓			
16.	o Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	✓		✓	
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance	✓		✓	
22.	Other				

Permit Number: C0070018
Inspection Type: COMPLETE

Inspection Date: Thursday, September 18, 2003

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The Division is currently reviewing one amendment for the Soldier Canyon Mine. It proposes the removal of text referring to a preparation plant and a refuse disposal site, neither of which was ever built. The OGM permit is current and valid through February 3, 2007. The UPDES permit is valid through March 31, 2006.

2. Signs and Markers

There are identification signs at the mine entrance and at the topsoil pile location. Each contains the required information. Disturbed area boundary and topsoil pile designation markers are in the proper locations.

3. Topsoil

The topsoil pile is stable and protected from sediment loss by vegetation and berms. There are no signs of significant erosion.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Ms. Vicky Miller conducted the second-quarter sediment pond inspection on May 13, 2003. She did not note any signs of instability or hazards and none were present during this inspection. There is some water in the pond due to recent precipitation.

4.d Hydrologic Balance: Water Monitoring

Canyon Fuel completed second-quarter water monitoring, but have not yet submitted the data. They plan to do so before the deadline of September 30. Third-quarter water monitoring is nearly complete.

4.e Hydrologic Balance: Effluent Limitations

Canyon Fuel provided hard copies of the second-quarter DMR data for review. There were no discharges during the quarter.

13. Revegetation

The re-vegetated topsoil pile has mostly shrubs and forbs growing on it, not many grasses. The vegetation is providing the necessary erosion control.

15. Cessation of Operations

The Soldier Canyon Mine is in temporary cessation. Canyon Fuel does not expect to resume operations for several years.

19. AVS Check

OGM completed an AVS check in May of 2003, noting no violations in the system.

Permit Number: C0070018
Inspection Type: COMPLETE

Inspection Date: Thursday, September 18, 2003

Page 4 of 4

20. Air Quality Permit

The Division of Air Quality issued a permit for Soldier Canyon on May 2, 1994. It remains valid and unchanged since that date.

21. Bonding and Insurance

The Certificate of Insurance is valid through July 31, 2004. It provides for \$500,000 aggregate and \$300,000 per each occurrence as required by the Coal Rules. The site is bonded for \$3,238,000. The Surety is Liberty Mutual Insurance Company, which has an A rating.